



TECHNICAL INFO N° 5

PRODUCTS USED IN LASER PRINTERS

HELPFUL TIPS & RECOMMENDATIONS

1. Sheets should be fed with paper grain at right angle with the drive rolls of the laser printer. Feeding problems are avoided when fed that way.
2. **On roll to sheet converting**, it is recommended to matrix strip the 4 edges of the Din A4 in order to :
 - avoid adhesive bleed with its consequences of sheets sticking together.
 - avoid adhesive built up on the drive rolls inside the printer.
 - enable easy manual dispensing.

3. LAY FLAT

Near the core, it may occur that the material presents a small curl; this may be easily handled with a curl break device (breaking bar) placed at the beginning of the converting machine.
The accepted edge lift of a sheeted product before end-use is 20 mm, in Din A4.

4. **Pack** the sheeted products in plastic wrappings.