



## TECHNICAL INFO N° 3

### THERMAL TRANSFER - THE CHOICE

**ARMOR RIBBON RECOMMENDATIONS FOR THE MACTac MATERIALS (maximum print speed).**

MATERIAL LIST	FLAT HEAD PRINTERS					CORNER EDGE PRINTERS		
	AWR 470	AWX 500	APR 5	AXR 7+	AXR 8	APR 600	AXR 600	AXR 800
VELLUM 75	12 IPS	9 IPS	8 IPS	4 IPS	NC	12 IPS	6 IPS	NC
CILdata	NC	NC	NC	NC	NC	NC	NC	NC
MACtrans I	12 IPS	10 IPS	9 IPS	6 IPS	NC	12 IPS	8 IPS	NC
MACtrans II	12 IPS	9 IPS	7 IPS	5 IPS	NC	12 IPS	8 IPS	NC
VELVET, MACcoat	10 IPS	8 IPS	8 IPS	6 IPS	NC	11 IPS	6 IPS	NC
MACthene 1029	10 IPS	8 IPS	11 IPS	5 IPS	7 IPS	12 IPS	8 IPS	NC
MACthene 1029 TC, 8529 TC, 1099 TC, 8599 TC	10 IPS	8 IPS	11 IPS	5 IPS	7 IPS	12 IPS	8 IPS	8 IPS
MACthene 8528 TC, 1028 TC	12 IPS	9 IPS	11 IPS	8 IPS	8 IPS	12 IPS	9 IPS	6 IPS
CAST PE 829 TC, 899 TC	10 IPS	8 IPS	11 IPS	5 IPS	7 IPS	12 IPS	8 IPS	8 IPS
MACthene 8598 TC, 1098 TC	12 IPS	10 IPS	12 IPS	9 IPS	7 IPS	12 IPS	9 IPS	6 IPS
MACtrans III	11 IPS	11 IPS	11 IPS	9 IPS	5 IPS	12 IPS	7 IPS	NC
MACtrans III SP	12 IPS	8 IPS	10 IPS	8 IPS	6 IPS	11 IPS	6 IPS	C
MACtrans Pro	11 IPS	11 IPS	11 IPS	9 IPS	5 IPS	12 IPS	7 IPS	NC
MACal 6952	11 IPS	7 IPS	11 IPS	6 IPS	6 IPS	12 IPS	NC	NC
MACal 8128	11 IPS	NC	7 IPS	7 IPS	NC	11 IPS	4 IPS	NC
MACal 8129	11 IPS	10 IPS	11 IPS	7 IPS	6 IPS	12 IPS	7 IPS	4 IPS
MACpropy 629 TC	12 IPS	11 IPS	12 IPS	7 IPS	10 IPS	12 IPS	11 IPS	9 IPS
MACpropy 699 TC	12 IPS	11 IPS	12 IPS	7 IPS	10 IPS	12 IPS	8 IPS	8 IPS
MACflex	11 IPS	8 IPS	9 IPS	6 IPS	NC	12 IPS	6 IPS	NC

NC = Not recommended